



SecureLock Coaxial Jack and Plug Connector Kits Product Manual

TABLE OF CONTENTS

•	Introduction	3
•	Assembly	5
•	Maintenance	11
•	Warranty & Return Information	11



INTRODUCTION

This document contains information on the operation, assembly, and maintenance of the CK-PXF and CK-PXM connector kits. This manual is an overview of the system and references the specific component manuals. User manuals are provided with the system for all configurable internal components.



Figure 1. PXF Coaxial Jack Connector Kit Materials





Part #	Connector Kit Parts	Max Temp.	Max Cable Diameter	Connector Kit Parts #
PXF		340 °F (171 °C)	0.12 in. (3,04 mm)	CK-PXF-1A CK-PXF-1B CK-PXF-1C CK-PXF-1D
	SecureLock Coaxial Jack Connector Kit			
РХМ		340 °F (171 °C)	0.12 in. (3,04 mm)	CK-PXM-1A CK-PXM-1B CK-PXM-1C CK-PXM-1D
	SecureLock Coaxial Plug Connector Kit			

Figure 1. Product Selection Guide



Assembly for PXF

1. Strip outer jacket of wire 0.39 in. and shield 0.13 in.



3. Slide the long and then short clear heatshrinks onto the cable. If no label is going to be affixed to the cable, the long heatshrink is unnecessary.



4. Slide the colored heatshrink onto the cable.



5. Slide the crimp ferrule onto the cable.



6. Fan out the shielding.





7. Solder the socket onto inner coaxial cable.



8. Slide connector onto the socket and cable.



9. Slide the crimp ferrule toward the connector, pushing down the shield over the connector.



10. Crimp with a 0.137 in. hex crimp.



11. Slide the colored heat shrink forward over the crimp.







13. Slide the shorter clear heat shrink forward onto the connector.





- 15. If using a label, affix it to the cable, and slide the longer clear heat shrink over it.
- 16. Use a heat gun to form the heat shrink to the cable over the label.





Assembly for PXM

1. Strip outer jacket of wire 0.39 in. and shield 0.13 in.



3. Slide the long and then short clear heatshrinks onto the cable. If no label is going to be affixed to the cable, the long heatshrink is unnecessary.



4. Slide the colored heatshrink onto the cable.



5. Slide the crimp ferrule onto the cable.



6. Fan out the shielding.







Solder the pin onto inner coaxial cable.

7.

9. Slide the crimp ferrule toward the connector, pushing down the shield over the connector.



10. Crimp with a 0.137 in. hex crimp.



11. Slide the colored heat shrink forward over the crimp.







13. Slide the shorter clear heat shrink forward onto the connector.





- 15. If using a label, affix it to the cable, and slide the longer clear heat shrink over it.
- 16. Use a heat gun to form the heat shrink to the cable over the label.





MAINTENANCE

Once the (product) has been installed, minimal maintenance will be required. Basic visual checks to ensure integrity should be made periodically.

General

There are no customer-replaceable parts. The product has been designed for trouble-free service under normal operating conditions.

WARRANTY & REFUND

Please visit www.ctconline.com to view a complete recapitulation of our warranty and refund policies.

CONTACT INFORMATION

Connection Technology Center, Inc. (CTC) 7939 Rae Blvd. Victor, NY 14564 1.585.924.5900 sales@ctconline.com www.ctconline.com



Мм-Ск-Рхм/Rev A