



WIRING DIAGRAM

CTC STANDARD

TRIAxIAL SENSORS



4 Pin MIL

Pin A Axis Y

Pin B Axis X

Pin C Axis Z

Pin D Common

